LOCKHEED AIRCRAFT CORPORATION		GINEERING ANGE PROI		<u> </u>	I. A. C 129				
DATE 28 NAY 1962	AF	FECTS:	WSF	°	P	ROJECT	x		
NAME OF MAJOR COMPONENT INSTRUMENT PANEL		OWEST SUE		į.	PART NO.	& MODEL	OR TYPE		
TITLE OF PROPOSAL:	E COCKPIT			<u>-</u>					
NATURE OF PROPOSAL:				·					
see P	AGE 2								
				٠					
							•		
					:				
REASON FOR PROPOSAL:			,			3	ž		
SEE PA	GE 2	•							
•									
	-		eas.						
						•			
							v V		
ES ADDITIONAL TIME					•	1 1 1 1 1			
ADDITIONAL FUNDING REQUI	· · · · · · · · · · · · · · · · · · ·	*			·				
ESTIMATED COST FOR KITS O	• .	SEE PAG	E 2			-	•		
ADDITIONAL FUNDING REQUI	RED :	8P-1922	(HOME)				- Mr		
EMS AFFECTED BY PROPOSAL:			4		•				
SAFETY MISSION PERFORM OPERATI		WEIGHT OR	TOOLS &	MAINTE-	SERVICE	FLIGHT	MAINTE		
EFFEC- TIVENESS ANCE PROCEDO	JRE CHANGE ABILITY	WEIGHT & BALANCE	SUPPORT EQUIPMENT	NANCE PROCEDURE	LIFE	MANUAL	MAINTE- NANCE MANUAL		
							X		
ST. MAN/HRS. REQ'D. TO ACCOMPL	ISH CHANG	E IN FIELD							
OURCE OF PARTS FOR KIT		AVA	LABILITY _	4	WEEKS AF	TER APPRO	JAVC		
IAC									
ISPOSITION OF SPARES AFFECTED) DDWstreen	40	79%				S		
M-500 TYPE CIRCUIT	DREAKEK.				Yes_				
VITIATED BY :		/1	OVED):	WSPOX	<u>- </u>				

T PAGE TOE 2

NATURE OF PROPOSAL

- 1. Change the cockpit circuit breakers from the present M-500 to the MS-25244 type.
- 2. Prepare and issue a Service Bulletin and purchase the necessary number of circuit breakers (approx. 25/kit).

REASON FOR PROPOSAL

The MS-25244 breakers "Pop-Out" when tripped whereas the M-500 breakers
"Pull-In" when tripped. The Contractor has been informed by the manufacturer
that this project is the only one that uses circuit breakers that pull in
when tripped. The tooling for this breaker is no longer able to produce
parts satisfactorily. Therefore, new tooling, in the amount of

vill have to be paid and also the manufacturer states that the unit cost

vill increase. The MS-25244 circuit breaker is presently being installed in
the new junction box in the Q-Bay at Phase II IRAN. Acceptance of this proposal

would mean standardization of circuit breakers. The MS-25244 breakers are
readily available and the unit cost is less than the present price of the
M-500 type breaker (approx. \$2.95). To avoid cockpit confusion, each ship
should have all breakers replaced at the same time.

ESTIMATED COST FOR KITS OR PARTS

Customer	#1	6 Kits	9
Customer	# 2	30 Kits	8

STAT

STAT